EUROLAN

**STEP 1:**

Insert wires into IDC's according to
the desired wiring configuration (T568B/T568A).
Terminate wires using punch down tool.
Make sure the tool is set to trim excess
wire as shown.

CUT

2 optional locations to screw
grounding wire (included).

**STEP 2:**

Snap keystone Jacks
Into patch panel.

STEP 3:

Recommended cable routing
for terminated modules.
Terminate cables in the direction
from A to B as indicated.

B

B

A

A

STEP 4:

Recommended cable routing
for patch cords.

eurolan.com
info@eurolan.se

EUROLAN

standard 19" rack

cable management

angled patch panel

screw

Concave Installation

Mount one side first then the other side.

STEP 1:
Pre-load screws onto the rack, and leave some space on the screws as shown.

STEP 2:
Mount the cable managements as shown, fit one side of concaves to the screws first, then adjust to mount the other side of concaves to the screws.

STEP 3:
Mount the angled patch panel in the same way in Step 2. Fasten all screws properly.

Screwdriver

Screw-hole Installation

Mount lower screws first then the upper screws.

STEP 1:
Mount angled patch panel and the lower cable management. Pre-load lower screws and leave some space on screws as shown.

STEP 2:
Between the gap of the rack and the angled patch panel, put in the upper cable managements as shown.

STEP 3:
Fasten all screws properly.

Screwdriver

eurolan.com

info@eurolan.se